

Connection of the interface adapter 99szksu to a USB interface:

First end all applications which are running on the PC.

Connect the controller to the PC with the supplied USB interface adapter. After you get the message "new hardware found", insert the included driver CD and select the respective folder according to your operating system.

Available are Win2000_XP_XP64, Win98_ME and Windows7_Vista.

Launch the installation from the CD in the windows dialog.

Following installation, the USB adapter appears in the windows system level as a further COM port.

During driver installation the desired COM port is requested.
WINPKS supports the COM ports from COM1 to COM99